Minnesota State Capitol Restoration ACEC Building Engineering and Construction Conference



Sean Cotton | Zachary Poynter | Kimberly Sandbulte
HGA Architects and Engineers
October 18, 2016











OUTLINE

- ► Introduction
 - Building & Project History
 - Existing Conditions
 - Initial Coordination
- ► Infrastructure
 - Basement
 - ► Vertical Distribution vaults, shafts, stairs
 - Attics
- Functionality & Life Safety
 - Lighting
 - Restrooms
 - ► Smoke Evacuation System
- ► Finishes Restoration & Preservation



INTRODUCTION:

A PROJECT 110 YEARS IN THE MAKING...

► Original construction completed in 1905









CASS GILBERT ARCHITECT 1859 - 1934

- ► Significant Buildings
 - ► Minnesota State Capitol
 - ► New York Custom House
 - ► Arkansas State Capitol
 - West Virginia State Capitol
 - Woolworth Tower
 - ► United States Supreme Court

Capitol Reaching a Tipping Point










- Previous work was done in a piecemeal approach
- Stone Restoration Ongoing Scaffolding
- ► Failing Mechanical
- ► Failing Electrical
- ► Failing Plumbing
- ► Failing Windows
- ► Limited Sprinkler System Coverage
- Accessibility Issues
- ► Security Concerns

Project Summary

- Building Exterior Marble Restoration
- New Roof
- Replace All Infrastructure:
 - ▶ HVAC Systems
 - Plumbing
 - Electrical
 - Lighting
 - ▶ Data, Telecom & Audiovisual
 - Security Systems
- Comprehensive Interior Restoration
- Site Improvements & Landscaping








Documenting Existing Conditions




- Laser Scan
- Defining Historic Zones
- MultiVista







Existing Structural Systems






Fig. 46. Section of End-construction Flat Arch with End-construction Skews and with Marble or Terrazo Finish, Illustrating Placing of Units and Methods of Making Concrete Fill





Fig. 43. Segmental Floor-arch, Illustrating Method of Protecting Exposed Portions of Girder

► Flat and segmental tile floor systems


Existing Structural Systems


► Guastavino timbrel arch construction




















Minnesota State Capital Restoration Preserving our past. Preparing our future.





Basement: Before/History












Basement: Underfloor Systems






Basement: Underfloor Systems







3 SECTION 1/2" = 1'-0"

Minnesota State Capital Restoration

ARCHITECTURAL INTEGRITY. BUILDING FUNCTIONALITY. LIFE SAFETY

Underpinning

Basement: Underfloor Systems










Basement: Above Floor Systems









Basement Systems


Basement: now






Minnesota State Capital Restoration Preserving our past. Preparing our future.








Minnesota State Capital Restoration Preserving our past. Preparing our future.


Vertical Distribution

Vertical Distribution: Vaults






Vertical Distribution: Vaults





Vertical Distribution: Vaults





Horizontal Distribution: Sleeves & Lintels









Horizontal Distribution:

Cutting and Coring







Service Elevator and Enclosed Exit Stair



Preserving our past. Preparing our future.

ARCHITECTURAL INTEGRITY. BUILDING FUNCTIONALITY. LIFE SAFETY


Elevator and Stair





Minnesota State Capital Restoration Preserving our past. Preparing our future.


New and Extended Stairs







Infrastructure









Minnesota State Capital Restoration Preserving our past. Preparing our future.



Attics





Existing Catwalk Access





Existing Catwalk Access





Minnesota State Capital Restoration


h

Plaster Hangers – House Attic






Plaster Hangers – House Attic




Preserving our past. Preparing our future.


Catwalk Access



Catwalk Access




版




Attics

All the Coordination in the World....





Functionality & Life Safety





Smoke Evacuation System






Minnesota State Capital Restoration

Preserving our past. Preparing our future.



Minnesota State Capital Restoration

Preserving our past. Preparing our future.











Minnesota State Capital Restoration Preserving our past. Preparing our future.







Wall Channeling & Sensitive Spaces









Data, Telecom, Electrical Devices

(Hearing Rooms)



Energy Efficiency Goals

- Minnesota B3, Buildings, Benchmarks, and Beyond
- 2030 Energy Standard
- ► Energy models currently predict this building will operate 60-70% better than the SB2030 goals.

How

- District Energy
- ► Fan wall AHU technology
- ▶ Full economizer






Restrooms

The original restrooms in the building were very unique with Tennessee Pink Marble walls and floors, wood doors, and nickel hardware. The stalls even had lights that lit when the stall door closed. Unfortunately many of those elements were gone or damaged, and the bathrooms needed to be made accessible. Plus, there was originally only one public restroom per floor, considering most of the building occupants in 1905 were male. The restoration project is adding restrooms so there will be adequate accommodations on every floor, in a consistent location so they are easier to find.



Finishes Preservation

Plaster Repair





Access - Scaffolding








Minnesota State Capital Restoration

版

Decorative Paint















Glass Elevator Fronts






Figure 1 Southeast elevator in the second floor, ca. 1970. Minnesota Historical Society audio-visual collection. no. FMP6.15Cp35.

Minnesota State Capital Restoration

Preserving our past. Preparing our future.





Skylights

OUT OF THE BUILDING'S 30 ORIGINAL SKYLIGHTS, 10 HAD BEEN COVERED WITH DROPPED CEILINGS. THE PROJECT HAS UNCOVERED AND IS RESTORING THEM

The skylights over the oval stair and grand stairs are composed of curved leaded and stained glass panels. 100 years of baking sunlight had caused the leading to lose its structural integrity and many of the glass pieces had cracked. Each curved panel was taken to a local artisan, Gaytee Glass, and a custom mold was built to match the curve. Then the leading was removed from the glass pieces and replaced. The Grand Stair skylights are 25 feet by 50 feet each!



Tile Floor Restoration





QUESTIONS?

THANK YOU!

SEE YOU AT THE GRAND OPENING FALL 2017!

