Desert -Borrego Springs



Tilting T (near Borrego Springs Resort)



Palm Canyon Drive (looking east toward Christmas Circle)



Palm Canyon Drive (east of Borrego Valley Rd)

Overview

The Borrego Springs Community Sponsor Group (BSCSG) and County staff concur on all Circulation Element road recommendations. Lowering the development intensity in the Desert Subregion produced a reduced need for roads—especially 4-lane roads. The proposed road network minimizes costs and environmental impacts when compared to the network that would be required to balance the infrastructure needs of the Existing General Plan. The proposed road network for the Desert Subregion will operate at and acceptable level of service (LOS).

Planning Group Preferences

The Community Sponsor Group endorsed the proposed road network.

Key Issues

Community Character

A pedestrian friendly village is important to the Borrego Springs community. The community members want more pedestrian friendly roads in the village than the wide 4-lanes roads called for in the Existing General Plan. The proposed road network, which is composed of 2-lane roads, better meets this community preference.

Minimize Costs

The proposed road network costs less to build and maintain than the classifications in the existing general plan road network.

Minimize Environmental Impacts


The proposed road network is less impactive to the surrounding environment than existing general plan road network.

Trials/Pathways

Road types with wider right-of way (ROW) were preferred for many of the roads in this area for trails and pathways.

Board Alternative Map Network

A separate CE road network is not recommended for the Desert-Borrego Springs subregion.









Figure DBS-3: Changes to Current CE Network



	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
1	Montezuma Valley Road (SF 1406) Segment: Ranchita to Palm Canyon Drive Existing Condition: 2 lanes (passing lanes in 2 areas) Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes) Possible passing lanes	Road Capacity – Proposed classification will operate at an acceptable LOS
2A	Palm Canyon Drive (SA 180) Segment: Montezuma Valley Road to Christmas Circle Existing Condition: 2 lanes Current Classification: Collector Road / Major Road (4 lanes)	Downgrade Classification 2.2A Light Collector with Raised Median (2+ lanes)	 Road Capacity – Proposed classification will operate at an acceptable LOS Support Land Use Goals – Community desires more pedestrian friendly road in the village than the Existing Circulation Element Classification
2B	Palm Canyon Drive (SA 180) Segment: Christmas Circle to Borrego Valley Road Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes)	Downgrade Classification 2.2A Light Collector with Raised Median (2+ lanes)	 Road Capacity – A short segment of Palm Canyon Drive may operate at LOS. However the proposed road classification for the town center than a 4-lane road. In addition, the proposed classification would operate at an acceptable LOS if the entire local road network were incorporated into the SANDAG traffic model. Build Community Consensus – Sponsor Group supports the recommendation because they desire a more pedestrian friendly road in the village Minimize Costs – Proposed road costs less to build and maintain than the classification in the Existing General Plan

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
2C	Palm Canyon Drive (SC 430) Segment: Borrego Valley Road to Peg Leg Road Existing Condition: 2 lanes + median Current Classification: Major Road / Collector Road (4 lanes)	Downgrade Classification 2.1D Community Collector with Improvement Options (2+ lanes) Possible trails/pathways	Road Capacity – Proposed classification will operate at an acceptable LOS
3	Christmas Circle (SA 175) Segment: Entire traffic circle Existing Condition: 2 lane traffic circle Current Classification: Major Road (4+ lanes)	Downgrade Classification 2.2E Light Collector (2 lanes) Note: This would be a 1-lane "Traffic Circle" with operational improvements (Since there is no road standard for traffic circles, Light Collector could be used)	 Build Community Consensus – Sponsor Group supports the recommendation, it is located within village, and the Community desires the 2-lane traffic circle be reduced to a 1-lane traffic circle and a drastically reduced road bed Support Land Use Goals – This area is not pedestrian friendly today (the park/ community activities are separated by two wide lanes and no crosswalks), and a reduced road bed is needed to improve pedestrian crossings and safety. One-lane traffic circle is supported by vitalization report.
4	Peg Leg Road (SC 450) Segment: Palm Canyon Drive to Borrego- Salton Seaway Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.1D Community Collector with Improvement Options (2+ lanes) Possible trails/pathways	 Road Capacity – Proposed classification will operate at an acceptable LOS Build Community Consensus – Sponsor Group supports the recommendation, especially because the right-of-way would still allow for trails/pathways

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
5	Borrego-Salton Seaway (SA 160) Segment: Peg Leg Road to Imperial County Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Minor Upgrade 2.1D Community Collector with Improvement Options (2+ lanes) Possible trails/pathways and/or passing lanes	Road Capacity – Proposed classification will operate at an acceptable LOS, and the right-of-way would still allow for desired trails/pathways
6A	Henderson Canyon Road (SC 420) Segment: Peg Leg Road to Di Giorgio Road Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Minor Upgrade 2.1D Community Collector with Improvement Options (2+ lanes) Possible trails/pathways	 Road Capacity – Proposed classification will operate at an acceptable LOS, and the right-of-way would still allow for desired trails/pathways Flower area Note: Wider right-of-way (ROW) provides option for future road improvements if needed, but a passing lane may not be appropriate in this location (flower viewing area)
6B	Henderson Canyon Road (SC 420) Segment: Di Giorgio Road to Borrego Springs Road Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
7A	Borrego Springs Road (SA 170) Segment: Henderson Canyon Road to Christmas Circle Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) / Rural Light Collector (2 lanes)	Downgrade / Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
7B	Borrego Springs Road (SF 1406) Segment: Christmas Circle to Yaqui Pass Road Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes) Intersection improvement	 Road Capacity – Proposed classification will operate at an acceptable LOS Note: Wider ROW provides option for future road improvements if needed; a passing lane may not be appropriate in this location, but intersection improvements should be included at Christmas Circle
7C	Borrego Springs Road (SA 190) Segment: Yaqui Pass Road to Highway 78 Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.1D Community Collector with Improvement Options (2+ lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS.
8	Ocotillo Circle / Lazy S Drive / Big Horn Road Segment: Palm Canyon Drive to Borrego Springs Road Existing Condition: 2 lanes Current Classification: Local Public Road	Minor Upgrade 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS. This road was added to the CE network because it carries school trips and links residential development areas to the main street and village
9A	Big Horn Road (SA 160) Segment: Borrego Springs Road to Di Giorgio Road Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
9B	Big Horn Road (SA 160) Segment: Di Giorgio Road to Borrego Valley Road Existing Condition: Unbuilt Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	 Road Capacity – The number of trips forecast for this area do not require a CE road Build Community Consensus – Sponsor Group supports the recommendation Minimize Costs – Deleting the unbuilt road costs will reduce future public costs
10A	Di Giorgio Road (SC 460) Segment: Henderson Canyon Road to Palm Canyon Drive Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Minor Upgrade 2.2D Light Collector with Improvement Options (2+ lanes) Possible trails/pathways	 Road Capacity – Proposed classification will operate at an acceptable LOS Build Community Consensus – Sponsor Group supports the recommendation, because wider right-of-way provides option for trails/pathways and future road improvements if needed
10B	Di Giorgio Road (SC 460) Segment: Palm Canyon Drive to Tilting T Drive Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
11A	Borrego Valley Road (SC 470) Segment: Henderson Canyon Road to Palm Canyon Drive Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
11B	Borrego Valley Road (SC 470) Segment: Palm Canyon Drive to Rango Way Existing Condition: 2-lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
11C	Borrego Valley Road (SC 470) Segment: Rango Way to Borrego Springs Road Existing Condition: Unbuilt (dirt road) Current Classification: Collector Road (4 lanes)	Delete CE Road	 Road Capacity – The number of trips forecasted for this area do not require a CE road Minimize Costs – Deleting the unbuilt road costs less than building a road that is not needed
12	Rango Way (SC 445) Segment: Borrego Valley Road to Yaqui Pass Road Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Minor Upgrade 2.2D Light Collector with Improvement Options (2+ lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
13A	Yaqui Pass Road (SF 1406) Segment: Rango Way to Highway 78 Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
13B	Yaqui Pass Road (SA 190) Segment: Rango Way to Palm Canyon Road Existing Condition: Unbuilt Current Classification: Collector Road (4 lanes)	Delete CE Road	 Road Capacity – The number of trips forecasted for this area do not require a CE road Minimize Costs – Deleting the unbuilt road costs less than building a road that is not needed Build Community Consensus – Sponsor Group recommended this segment to be deleted as a result of previous project level environmental analysis Minimize Environmental Impacts – Deleting the unbuilt road is less impactive to the sensitive habitat found in this area
14A	Tilting T Drive (SC 440) Segment: Borrego Springs Road to Di Giorgio Road Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
14B	Tilting T Drive (SC 440) Segment: Di Giorgio Road to Borrego Valley Road Existing Condition: 2 lanes + median Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2B Light Collector with Continuous Turn Lane (2+ lanes)	 Road Capacity – Proposed classification will operate at an acceptable LOS Minimize Costs – Proposed road classification is more consistent with the built road condition and the forecasted need for the Borrego Country Club Specific Plan Area

	CE Road Segment	Road Network Recommendations	Basis for Staff Recommendation
15A	Highway 78	Downgrade Classification	Road Capacity – Proposed classification will operate at an acceptable LOS
	Segment: North Mountain to Yaqui Pass Road Existing Condition: 2 lanes	2.2D Light Collector with Improvement Options (2+ lanes)	will operate at all acceptable LOS
	<u>Current Classification</u> : Major Road (4+ lanes)	Possible passing lanes	
15B	Highway 78	Downgrade Classification	Road Capacity – Proposed classification
	Segment: Yaqui Pass Road to Imperial County Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes)	2.1D Community Collector with Improvement Options (2+ lanes) Possible passing lanes	 will operate at an acceptable LOS Minimize Costs – Proposed road costs less to build and maintain than the classification in the existing general plan
16	Great Southern Overland Stage Route of 1849 (SA 200)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – Proposed classification will operate at an acceptable LOS
	Segment: Entire segment Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)		
17	Old Kane Springs Rd (SC 510) Segment: Entire segment Existing Condition: Unbuilt (portions dirt roads) Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	Road Capacity – The number of trips forecast for this area do not require a CE road
18	Split Mountain Road (SA 210) Segment: Entire segment Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Delete CE Road	See 17