

New Mexico TTCP Training and Certification Schedule

(Updated September 1st, 2026)

Lab 1 (L1) = David Lara's Lab

Lab 2 (L2) = Austin Walker's Lab

Classroom 1 (C1) = Old North ACNM Classroom

Classroom 2 (C2) = New North Classroom (east)

Classroom 3 (C3) = New North Classroom (west)

Classroom 2 & 3 (C2/3) = New Combined Classrooms

Note: All FIVE lab/classroom locations are at the ACNM/TTCP facility at 6135 Edith, NE, Alb.

September 2026

1-3	8:00 am	HMA Training	FULL	L1
8-9	8:00 am	Soils Training	15	L2
8-9	8:00 am	Nuclear Densometer <u>Training</u> and Radiological Safety Certification	18	C1
10	8:00 am	Inertial Profiler Inspector Certification	25	C2/3
10-11	8:00 am	Concrete Training	15	L2
14-16	8:00 am	Aggregate Certification	FULL	L2
15-17	8:00 am	HMA Certification	FULL	L1
21-22	8:00 am	Soils Certification	15	L2
22-23	8:00 am	Nuclear Densometer Certification	5	C1
23-24	8:00 am	Concrete Certification	6	L2
9/28-10/1	8:00 am	Aggregate Training	15	L2
9/29-10/1	8:00 am	HMA Training	8	L1

October 2026

1	8:00 am	Seeding Inspector Certification	18	C1
5-6	8:00 am	Soils Training	15	L2
6-7	8:00 am	Nuclear Densometer <u>Training</u> and Radiological Safety Certification	18	C1
7-8	8:00 am	Concrete Training	15	L2
13-15	8:00 am	Aggregate Certification	15	L2
14-16	8:00 am	HMA Certification	8	L1

19-23 District 2 Fast Track Certification Roswell, NM Contact Manuel Ramirez – TTCP

Administrator for More Information

19-20	8:00 am	Soils Certification	15	L2
20-21	8:00 am	Nuclear Densometer Certification	18	C1
21-22	8:00 am	Concrete Certification	15	L2
10/26-10/29	8:00 am	Aggregate Training	15	L2

November 2026

2-3	8:00 am	Soils Training	15	L2
3-5	8:00 am	HMA Training	8	L1
4-5	8:00 am	Concrete Training	15	L2
9-10	8:00 am	Nuclear Densometer <u>Training</u> and Radiological Safety Certification	18	C1
12	8:00 am	Pile Driving Inspector Certification	18	C1
16-18	8:00 am	HMA Certification	8	L1
16-17	8:00 am	Soils Certification	15	L2
18-19	8:00 am	Concrete Certification	15	L2
23-24	8:00 am	Nuclear Densometer Certification	18	C1
23-25	8:00 am	Aggregate Certification	15	L2
11/30-12/03	8:00 am	Aggregate Training	15	L2

11/30-12/4 District 1 Fast Track Certification Las Cruces, NM Contact Manuel Ramirez – TTCP

Administrator for More Information

December 2026

1-2	8:00 am	Nuclear Densometer <u>Training</u> and Radiological Safety Certification	18	C1
7-8	8:00 am	Soils Training	15	L2
8-10	8:00 am	HMA Training	8	L1
9-10	8:00 am	Concrete Training	15	L2
10	8:00 am	Drilled Shaft Inspector Certification	25	C2/3
14-17	8:00 am	ATTI-TTCP Reciprocity Certification - Contact Manuel Ramirez – TTCP Administrator for More Information		

For TTCP and ACNM Class Registration Please Contact:

Ashley Primera aprimera@aconm.org (505) 344-2072, ext. 10

- **Please cancel at least one working day (24 hours) prior to the start of class, if the one working day cancellation policy is not met a \$100.00 no show fee will be applied.**
- Please be aware that the fourth column of this schedule shows “Spots Available” and that represents the number of seats that are available for that class on the date of this schedule. Seats may continue to fill up and some classes may be FULL before the next updated TTCP Schedule is sent out.
- All NMDOT personnel shall schedule through their District TTCP Training Liaison.
- Remember your OJT documentation when you come to TTCP for Certification.
- **NOTE: For participation in the Nuclear Densometer Training/Certification, you must bring your personal monitoring badge provided by your employer or District representative. NMED no longer allows TTCP to use loaner badges for Nuclear Densometer Training/Radiological Safety Certification or Nuclear Densometer Certification. If the scheduled technician attending either of these classes does not have their assigned monitoring badge by the time the hands-on demonstration is done, then they cannot complete Nuclear Densometer Training/Certification NO EXCEPTIONS.**